



Frame Verification Chart



Legend

—○— = 180 Line Symbol
N_s = Single vision
N_{p16} = Progressive 16
N_{p18} = Progressive 18
N_{om} = Office Meeting
N_{oc} = Office Computer

50 = 1.50 Plastic (above nasal 180 Line Symbol)
53 = 1.53 Trivex (above nasal 180 Line Symbol)
59 = 1.59 Polycarbonate (above nasal 180 line symbol)
60 = 1.60 High Index (above nasal 180 line symbol)
67 = 1.67 High Index (above nasal 180 line symbol)
74 = 1.74 High Index (above nasal 180 line symbol)
200 = Add Power (Range 050-400)

To print this measuring chart at the correct size from Acrobat Reader:

1. Go to File, then select **Print**
2. Under Page Sizing & Handling options, select **Actual Size**
3. Click on **Print** button to print

Note: Chart measurements will be incorrect if you select "fit" or other page-scaling options.

It is recommended to verify the printed chart is the correct size with a ruler.